

BUILDING SAFETY CERTIFICATENo. 49Dated: 16.04.2024

It is certified that the existing building **VIVEKANAND SR. SEC. SCHOOL** (Name of the building or premises) at **VILLAGE BAWWA, TEHSIL KOSLI, DISTRICT REWARI, HARYANA** (Address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	3	NIL	NIL	NIL	NIL	NIL

The building is owned/occupied by **VIVEKANAND SR. SEC. SCHOOL** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **OFFICE OF SUPERINTENDING ENGINEER REWARI CIRCLE PWD [B & R] REWARI** (Name of Department/ Govt.) on **08.04.2024** (date of inspection) in the presence of **MR. RAJEEV KUMAR, VIVEKANAND SR. SEC. SCHOOL, VILLAGE BAWWA, TEHSIL KOSLI, DISTRICT REWARI, HARYANA** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from **08.04.2024** for a period of **THREE (3)** years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on **15.04.2024** at **REWARI** by **MR. V.S. MALIK**

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal

Name

Designation

Name & Address of Department/ Office: _____

V. Malik
16/4/24
SUPERINTENDING ENGINEER
REWARI CIRCLE PWD [B & R]
REWARI

TO,
VIVEKANAND SR. SEC. SCHOOL,
VILLAGE BAWWA, TEHSIL KOSLI,
DISTRICT - REWARI, HARYANA